



CODE ENFORCEMENT BOARD HEARING AGENDA

SEPTEMBER 27, 2016 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code._

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: • Patrick McGee, Chair • Mark Booth, Vice Chair • Joan Hinton • Howard Nelson • Lakhi Mohnani • Peter Cooper • Joshua Miron (alternate) • Robert Smith (alternate) • Michael Madfis (alternate) • Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.



HEARING SCHEDULED

CASE NO: CE12050146 CASE ADDR: 1336 NE 1 AVE

OWNER: AMERICAN REAL ESTATE STRATEGIES FUND LP

INSPECTOR: JOSE ABIN

VIOLATIONS: 9-308(a)

THE ROOF HAS NOT BEEN MAINTAINED IN A SAFE, SECURE MANNER.

FBC(2010) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

- 1. WINDOWS AND DOORS WERE REPLACED.
- 2. THERE ARE STRUCTURAL ALTERATIONS IN THE REAR OF THE PROPERTY. A FLORIDA ROOM WAS CONVERTED INTO LIVING AREA. WINDOW AREAS WERE CLOSED WITH WALLS.
- 3. INTERIOR ALTERATIONS WERE DONE TO CONVERT THE PROPERTY FROM A DUPLEX TO A FOURPLEX.
- 4. A WALL A/C WAS REPLACED. THE OPENING WAS ALTERED AND THE UNIT WAS NOT INSTALLED IN A SECURE MANNER.

FBC(2010) 105.4.5

THE PREMISE WIRING HAS BEEN ALTERED.

FBC(2010) 105.4.11

A WALL A/C UNIT WAS REPLACED WITHOUT BEING ADEQUATELY BEING SECURED.

FBC(2010) 110.9

WORK WAS COVERED UP WITHOUT FIRST HAVING OBTAINED THE REQUIRED INPSECTION APPROVALS.

FBC(2010) 111.1.1

THE NATURE OF THE USE WAS CHANGED FROM A DUPLEX TO A FOURPLEX WITHOUT HAVING OBTAINED A CERTIFICATE OF OCCUPANCY.

FBC(2010) 1604.1

THE STRUCTURAL ALTERATIONS ARE NOT DESIGNED OR BUILT ACCORDING TO THE STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

FBC(2010) 709.1 6.

THE FIRE SEPARATION BETWEEN THE UNITS HAS NOT BEEN MAINTAINED.

CASE NO: CE15080382 CASE ADDR: 2151 NW 29 TER

OWNER: KINGS, TERRY JR EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. AFTER FIRE, INTERIOR OF DWELLING HAS BEEN DEMOLISHED. WALL AND CEILING COVERINGS REMOVED.

2. ELECTRICAL AND PLUMBING FIXTURES HAVE BEEN ALTERED AND/OR REMOVED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15091002 CASE ADDR: 1135 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV BROWARD CHILDR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PAVED AND STRIPED PARKING AREA WITHOUT ACQUIRING THE REQUIRED PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15091014

CASE ADDR: 225 S FTL BEACH BLVD
OWNER: L & A BEACH HOLDINGS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS RETAIL SPACE HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CHANGE OF USE TO A RESTAURANT WITHOUT OBTAINING THE REQUIRED PERMIT AND CHANGE OF OCCUPANCY TO MAXIMUM OF 200 WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY.

CASE NO: CE15111058 CASE ADDR: 822 SW 26 CT

OWNER: GONZALEZ, LUIS E MARTELL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. INTERIOR REMODEL NOT LIMITED TO KITCHEN AND BATHROOM
- 2. REPLACING WALLBOARD IN KITCHEN.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

 PLUMBING FIXTURES IN KITCHEN AND BATHROOM VANITY AND TOILET.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. REPLACEMENT OF ELECTRICAL BREAKER PANEL, FIXTURES, SWITCHES, OUTLETS AND WIRING FOR A/C AIR HANDLER AND COMPRESSOR.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. REPLACEMENT OF AIR-HANDLER EVAPORATOR UNIT AND EXTERIOR CONDENSER/COMPRESSOR UNIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF 2 EXTERIOR DOORS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16011458

CASE ADDR: 2307 N OCEAN BLVD OWNER: KERR-ROLLE, SWABY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

REMODELING OF STRUCTURE, INTERIOR AND EXTERIOR:

- 1. REMODELING INTERIOR WALL, REMOVING WALL COVERING AND REINSTALLING THROUGHOUT INCLUDING BATHROOMS, KITCHENS AND OTHER LIVING AREAS.
- 2. INSTALLED PERMANENT STRUCTURE ON EXTERIOR WALLS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM. THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE

FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF PLUMBING FIXTURES INCLUDING TOILETS, FAUCETS, PLUMBING LINES, VALVES, WASTE LINES. PLUMBING ASSOCIATED WITH BATHROOM AND KITCHEN REMODELING.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION AND REPLACEMENT OF FIXTURES, OUTLETS, SWITCHES, BREAKER PANELS AND DISCONNECTS.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM. THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ADDING/ALTERING THE COOLING AND HEATING SYSTEM.
- 2. ALTERING KITCHEN AND BATHROOM EXHAUST SYSTEM.

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS.

FBC (2014) 105.3.1.5

SUBMIT DRAWINGS AND A SCOPE OF WORK COVERING STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

ONSITE INSPECTION WILL BE REQUIRED TO VERIFY PERMIT APPLICATION REQUIREMENTS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF MULTI-FAMILY TO ASSIGNED LIVING FACILITY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT

CASE NO: CE16030296
CASE ADDR: 2370 NW 26 ST
OWNER: BENJAMIN, ERNST

BENJAMIN, ROSE MARIE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACED ROOF DECKING WITH STRIPS OF 5 INCH PLYWOOD.
- 2. MODIFIED ROOF RAFTERS BY SCABBING PIECES OF WOOD.
- 3. STRUCTURAL REPAIRS TO ROOF STRUCTURE REQUIRING ENGINEERING.
- 4. CEILING DRYWALL COVER HAS BEEN REPLACED THROUGHOUT THE HOUSE.

FBC (2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16032109
CASE ADDR: 601 SW 17 ST
OWNER: C4NAVIGATOR LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND

WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED NEW IMPACT WINDOWS AND DOORS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED

OCCUPANCY CLASSIFICATION OF TWO FAMILY DUPLEX TO A 5 FAMILY FIVE-PLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE

BUILDING DEPARTMENT.

CASE NO: CE16050226

CASE ADDR: 728 NW 6 AVE # A OWNER: CASALE, ROSANNE D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. FRAMED AND INSTALLED DRYWALL IN OFFICE

ENCLOSURE IN THIS WAREHOUSE.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK

DONE.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLED NEW ELECTRICAL CIRCUITRY AND FIXTURES, INCLUDING LOW VOLTAGE CIRCUITS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED SPLIT A/C MECHANICAL SYSTEM.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050288 CASE ADDR: 304 SW 22 ST

OWNER: CONCESSION MANAGEMENT LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ROOF STRUCTURAL REPAIRS.
- 2. DRYWALL REPAIRS IN THE KITCHEN.
- 3. WALL COVERING IN BATHTUB AREA REMOVED AND NEW TILEBACKER BEING INSTALLED.
- 4. SHED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. NO PERMIT FOR FENCE IN PERMIT HISTORY.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW PLUMBING FIXTURES IN BATHROOM AND KITCHEN.
- 2. WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW ELECTRICAL FIXTURES, SWITCHES AND OUTLETS.
- 2. NOT LIMITED TO REWIRING AND BREAKER PANEL CHANGEOUT AND ALTERATIONS.

FBC (2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050556

CASE ADDR: 2506 BARCELONA DR OWNER: WAYNE INVESTMENTS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 101.4.4.1

- 1. BUILT SEAWALL AND BLOCKED OUTFALL TO STORMDRAIN.
- 2. ALLOWED CONSTRUCTION MATERIAL TO BLOCK STORMDRAIN.

FBC(2014) 101.4.4.1.1

THIS CONDITION HAS CAUSED THE WATER RUNOFF INTO THE STORMDRAIN TO BACK UP INTO THE STREET, DRIVEWAYS, WALKWAYS AND ADJACENT PROPERTIES.

FBC(2014) 101.4.4.2

DUE TO STORMDRAIN BLOCKAGE WITH CONSTRUCTION MATERIAL AND THE CLOSING OF THE SEAWALL OUTFALL, THIS CONDITION HAS CAUSED THE STREETS TO UNNECCESSARILY FLOOD CAUSING A NUISANCE TO THE PUBLIC AND PRIVATE PROPERTIES.

CASE NO: CE16050712 CASE ADDR: 2308 NW 6 CT

OWNER: SANTORSOLVA, VITO MICHELE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED HURRICANE SHUTTERS ON EXTERIOR WALL

OPENINGS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT A/C MECHANICAL SYSTEM.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF CHAIN LINK FENCE.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050812 CASE ADDR: 1483 SW 18 AV

OWNER: ERICKSON, RICHARD P

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED AND ATTACHED STRUCTURE TO SIDE OF

DWELLING ENCROACHING ON SETBACK.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16051917

CASE ADDR: 1600 POINSETTIA DR

OWNER: BFA FLORIDA LAND TR #20

LBS2016 FAM HOMES LLC TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURAL MODIFICATIONS TO THE INTERIOR STRUCTURE OF THIS BUILDING.

- 2. MODIFYING THE ORIGINAL FLOOR PLAN OF THE INTERIOR OF THE DWELLING.
- 3. STORAGE SHED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. INSTALLATION AND REPLACEMENT WITH NEW PLUMBING FIXTURES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION AND REPLACEMENT OF ELECTRICAL FIXTURES AND REWIRING.
- 2. BREAKER PANEL REPLACEMENT WITH NEW CIRCUITS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. MECHANICAL ALTERATIONS BEING DONE TO THE MECHANICAL SYSTEM AND DUCT WORK OF THE STRUCTURE.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE WILL REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16060517
CASE ADDR: 1042 NW 8 AV
OWNER: CM3 HOMES LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. NEW INSTALLATION OF 2 SPLIT CENTRAL A/C
MECHANICAL SYSTEMS. COMPRESSOR FOR FRONT UNIT
MANUFACTURED DATED MAY 2008. COMPRESSOR FOR REAR
UNIT DATED JANUARY 2009.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK
DONE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF KITCHEN AND VANITY SINKS.
- 2. NEW KITCHEN CABINETS AND VANITY CABINET.
 NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF RECEPTACLES. ONE OVER THE KITCHEN SINK IS UNVERIFIED AS BEING IN GFI CIRCUIT. REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6), 210.8 (B) (5) SINKS AND 210.8 (B) (6) INDOOR WET LOCATIONS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16071899

CASE ADDR: 4040 GALT OCEAN DR

OWNER: OCEAN MANOR CONDO ASSOC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A THIRD TIKI HUT WHEN ONLY 2 HAVE BEEN PERMITTED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. INSTALLED WASTE OR GREASE LINE THAT IS DISCHARGING DIRECTLY INTO FLOOR DRAIN.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. NEW ELECTRICAL CIRCUITS AND RECEPTACLES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 116.2.1.2.5

ELECTRICAL SYSTEM HAS BEEN MODIFIED WITHOUT PERMITS.

FBC (2014) 116.2.1.2.6

INSTALLED WASTE OR GREASE LINE THAT IS DISCHARGING DIRECTLY INTO FLOOR DRAIN.

CASE NO: CE16011731 CASE ADDR: 1418 NW 11 PL

OWNER: PYRAMID CLASSICS INC

INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

ON 1/22/16 WHILE AT A PROPERTY ACROSS FROM THIS RESIDENCE I NOTICED THE FRONT DOOR OPEN AND WORK BEING DONE. I CHECKED THE COMPUTER FOR PERMITS BUT FOUND NO OPEN OR RECENT PERMITS. I WENT TO THIS SITE AND FOUND THE FOLLOWING WORK IN PROGRESS:

- 1. NEW KITCHEN CABINETS INSTALLED.
- 2. KITCHEN SINK REPLACED.
- 3. NEW ELECTRICAL BREAKER PANEL INSTALLED IN THE KITCHEN.
- 4. BATHROOM FIXTURES REPLACED.
- 5. SOFFITS CONSTRUCTED WITH DUCT WORK INSTALLED FOR AN A/C SYSTEM. THIS WORK EXTENDED FROM THE LINEN CLOSET NEXT TO THE BATHROOM INTO THE GARAGE.
- 6. THE GARAGE HAS NEW DRYWALL INSTALLED.
- 7. THE WINDOWS HAVE BEEN REPLACED BY THE PREVIOUS OWNER.

CASE NO: CE16020537 CASE ADDR: 5570 NW 10 TER

OWNER: 5551 NW 9TH AVE 1-5 LLC

INSPECTOR: FRANK ARRIGONI
PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THERE HAS BEEN A COMPLETE DEMOLITION OF THE 5112 SQ.FT.

STRUCTURE LOCATED ON THIS PROPERTY WITHOUT

OBTAINING THE REQUIRED PERMITS.

FBC(2014) 110.6

REQUIRED INSPECTIONS HAVE NOT BEEN DONE.

CASE NO: CE15101776

CASE ADDR: 745 MIDDLE RIVER DR

OWNER: DHALLA, MANDEEP K & MANDEEP S

INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

ON 2/11/14 AN APPLICATION FOR SEAWALL CAP AND DOCK

WAS SUBMITTED TO THE BUILDING DEPARTMENT, NO

PERMIT WAS ISSUED.

1. THE DOCK AND FINGER PIER HAVE BEEN REPLACED AND

WAS EXTENDED IN WIDTH. NO PERMIT CAN BE FOUND FOR

THIS WORK.

FBC (2014) 110.6

APPROVAL REQUIRED. NO WORK SHALL BE DONE ON ANY

PART OF A BUILDING OR STRUCTURE OR ANY,

ELECTRICAL, MECHANICAL OR PLUMBING INSTALLATION
BEYOND THE POINT INDICATED HEREIN ABOVE FOR EACH
SUCCESSIVE INSPECTION UNTIL SUCH INSPECTION HAS
BEEN MADE AND THE WORK APPROVED AND THE INSPECTOR

HAS SO INDICATED ON THE PERMIT CARD OR AN

INSPECTION RECORD PAD AT THE JOB SITE WHICH HAS

BEEN APPROVED BY THE BUILDING OFFICIAL.

CASE NO: CE16040400

CASE ADDR: 3000 E COMMERCIAL BLVD

OWNER: GORDON, MICHAEL H INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST

OBTAINING A PERMIT.

1. ROOFTOP A/C UNIT HAS BEEN REPLACED.

CASE NO: CE16040644

CASE ADDR: 325 ISLE OF CAPRI

OWNER: GALLUZZO, GEORGE R JR & MELISSA

INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THE PROPERTY HAS BEEN ALTERED IN THE FOLLOWING

MANNER.

1. THE DOCK HAS BEEN REPLACED ON THE EXISTING PILING AND STAIRS ADDED TO THE SOUTH END.

FBC(2014) 105.3.1.4.4

1. WATER LINES INSTALLED ON DOCK

FBC(2014) 105.3.1.4.5

1. ELECTRICAL SERVICE ADDED TO DOCK

FBC(2014) 110.6

THE REQUIRED INSPECTIONS FOR THIS WORK WERE NOT

DONE.

CASE NO: CE16041975

CASE ADDR: 10 S FEDERAL HWY

OWNER: SE BROWARD & FEDERAL LLC

INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.11

THE ROOFTOP A/C UNITS ON THIS STRUCTURE HAVE BEEN REPLACED WITHOUT PERMITS. MANUFACTURING DATES ARE 8/2010 AND 9/2010. THE DATE THE LAST PERMIT WAS ISSUED FOR A/C REPLACEMENT WAS 5/13/05 AND IS

VOID.

CASE NO: CE15111675

CASE ADDR: 39 CASTLE HARBOR ISLE

OWNER: LECLAIR, DANIEL INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BOAT LIFT INSTALLATION.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15122005

CASE ADDR: 1731 NW 7 TER
OWNER: THOMAS, JUSTIN DERRICK

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. CARPORT ENCLOSURE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16060309 CASE ADDR: 1845 SW 4 AV

OWNER: BREEZE SERVICES CORP INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE INSTALLATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16031509
CASE ADDR: 2220 SW 33 TER
OWNER: JONES, JENNIFER
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE REPAIRS OR ALTERATIONS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16031396

CASE ADDR: 2829 NE 30 ST #205 OWNER: VAHER, ENNO & CARMEN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF THE KITCHEN AND BATHROOM BEING REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071982

CASE ADDR: 333 SUNSET DR # 108 OWNER: GUERRERA, FRANCESCA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

CASE NO: CE16080443
CASE ADDR: 2101 NE 60 ST
OWNER: GOSSELIN, GENE

BREWER, DANIEL

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL AND POOL REMODEL WITH A NEW PAVER DECK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16080753

CASE ADDR: 14 ISLA BAHIA DR
OWNER: GROSVENOR, JUDSON

J MARK GROSVENOR T ETAL

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. EXTENSIVE ALTERATIONS MADE SUCH AS STEEL BEAMS INSTALLED, FRAMING, DRYWALL, A FULL INTERIOR RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT AT A MINIMUM WILL APPLY. BECAUSE OF THE SEVERITY OF THE SCOPE OF WORK, THE DOLLAR AMOUNT OF THE IMPROVEMENTS BEING MADE AND THE BLATANT ATTEMPT TO CIRCUMVENT THE REQUIREMENTS OF THE FLORIDA BUILDING CODE AND THE CITY OF FORT LAUDERDALE BUILDING DEPARTMENT THIS CODE CASE IS SUBJECT TO FOUR TIMES THE FEE ON ALL REQUIRED AFTER THE FACT PERMITS THAT WILL BE REQUIRED FOR COMPLIANCE FOR THIS CODE CASE.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16080928

CASE ADDR: 2864 NE 33 CT # 108

OWNER: SADOWSKI, PAUL & SANDRA L

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOMS REMODELLED INCLUDING FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY/CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16081019
CASE ADDR: 718 SE 13 ST
OWNER: MAGNA PMC LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. DEMOLITION AND ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING DEMOLITION AND ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL DEMOLITION AND ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16072243
CASE ADDR: 1027 NE 13 AV
OWNER: NIKAJ, ESMERALDA

NIKAJ, NESTI

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. THE INSTALLATION, ALTERATION OR REPAIR OF ANY SANITARY PLUMBING, WATER SUPPLY, LAWN SPRINKLER OR GAS SUPPLY SYSTEM, AS PROVIDED IN THE FBC PLUMBING, AND/OR FBC FUEL GAS.

FBC(2014) 105.3.1.4.5

THE INSTALLATION, ALTERATION OR REPAIR OF ANY ELECTRICAL WIRING OR EQUIPMENT, AS PROVIDED IN CHAPTER 27-ELECTRICAL SYSTEMS AND THE N.E.C.; EXCEPT AS ALLOWED IN SECTION 105.17 OF THIS CODE.

1. ANY ALTERATION OR EXTENSION OF AN EXISTING WIRING SYSTEM IS NOT CONSIDERED TO BE MAINTENANCE OR REPAIR.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

1. NEW A/C UNIT INSTALLED

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE08070448

CASE ADDR: 1431 NW 11 PL

OWNER: DRAGOSLAVIC, GORAN

DRAGOSLAVIC, TERESA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK

ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.

- 2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WERE COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.
- 3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.
- 4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE14051440
CASE ADDR: 1663 NW 15 TER
OWNER: ALLADIN, VANEL
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE DWELLING'S OPENINGS WERE BOARDED AND THE WOOD HAS BEEN REMOVED.

2. NEW WINDOWS AND EXTERIOR DOORS WERE INSTALLED ON THEM.

3. INTERIOR UPGRADE INSIDE THE KITCHEN AND BATHROOMS AREAS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15102378

CASE ADDR: 680 TENNIS CLUB DR # 301

OWNER: LOPEZ, DENNIS R

LOPEZ, DENNIS A

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. WORK W/O PERMIT IN PROGRESS, THE INTERIOR OF THE UNIT WAS GUTTED WITHOUT A DEMOLITION PERMIT.
- 2. RENOVATION ARE BEING DONE AS FRAMING, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE PROPER PERMITS AND INSPECTIONS, INCLUDING THE OPENINGS ON THE FIRE PARTITONS.
- 3. WINDOWS WERE REPLACED.
- 4. CENTRAL A/C IS BEING REPLACED AND THE DUCT WORK IS BEING ALTERED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15102497
CASE ADDR: 1213 NW 14 ST
OWNER: MOONEY, CHRISTINA
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNER'S DRAWINGS WITH THE WINDS PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC(2014) 2224.1 FOR CHAIN LINK AND FBC(2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT LOCATION.

1. A WOOD FENCE WAS ERECTED WITHOUT THE REQUIRED

PERMITS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15102466
CASE ADDR: 2871 NW 18 CT
OWNER: PETUDO LLC
ARRITITI TR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

WORKING WITHOUT PERMITS, AS:

- 1. INTERIOR RENOVATIONS IN PROGRESS.
- 2. THE REAR FLATROOF DECK IS BEING REDONE WITHOUT PERMITS.
- 3. THE DWELLING WAS REROOF WITH A PERMIT 07010493
 THAT WAS LEFT TO EXPIRE AND TODAY IS WORK WITHOUG
- 4. TWO OPENINGS WERE CUT ON THE GARAGE WALL AND TWO WINDOWS WERE PLACED ON IT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13051997 CASE ADDR: 1515 NW 7 AVE

OWNER: YUTHASUNTHORN, CHANCE

YUTHASUNTHORN, SIRILUK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE

FOLLOWING MANNER WITHOUT A PERMIT:
1. NEW WINDOWS HAVE BEEN INSTALLED.

2. A KITCHEN REMODELING PROJECT IS IN PROGRESS.

3. A BATHROOM REMODELING PROJECT IS IN PROGRESS.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED BY THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14090738
CASE ADDR: 1001 NW 14 CT
OWNER: 2771 LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS, AS FOLLOWS:

- 1. THIS PROPERTY IS BEING UPGRADED.
- 2. WINDOWS AND DOORS ARE BEING REPLACED IN SOME OF THE OPENINGS.
- 3. INTERIOR WORK OR REMODELING IS IN PROGRESS WITH NEW CABINETS IN THE KITCHEN AND BATHROOM AREAS. NEW ELECTRICAL AND PLUMBING FIXTURES BEEN INSTALLED.
- 4. CENTRAL DUCTED A/C HAS BEEN INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15051829
CASE ADDR: 1804 NW 16 CT
OWNER: TUCHOW, TYLER
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE CARPORT HAS BEEN ENCLOSED.
- 2. PLUMBING, ELECTRICAL & MECHANICAL WORK HAVE BEEN DONE WITHIN THE ENCLOSED CARPORT FOR A BATHROOM AND WASHER AND DRYER.

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLYING THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC (2010) 111.1.1

USE AND OCCUPANCY. NO BUILDING OR STRUCTURE SHALL BE USED OR OCCUPIED, AND NO CHANGE IN THE EXISTING OCCUPANCY CLASSIFICATION OF A BUILDING OR STRUCTURE OR NATURE OR USE OR PORTION THEREOF SHALL BE MADE UNTIL THE BUILDING OFFICIAL HAS ISSUED A CERTIFICATE OF OCCUPANCY THERE FOR AS PROVIDED HEREIN. SAID CERTIFICATE SHALL NOT BE ISSUED UNTIL ALL REQUIRED ELECTRICAL, GAS, MECHANICAL, PLUMBING AND FIRE PROTECTION SYSTEMS, AND PROVISIONS OF FFPC HAVE BEEN INSPECTED FOR COMPLIANCE WITH THE TECHNICAL CODES AND OTHER APPLICABLE LAWS AND ORDINANCES AND RELEASED BY THE BUILDING OFFICIAL. ISSUANCE OF A CERTIFICATE OF OCCUPANCY SHALL NOT BE CONSTRUED AS AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION.

CASE NO: CE15070098
CASE ADDR: 5200 NW 31 AVE

OWNER: VILLAS AT LAKEVIEW CONDO ASSN IN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT STORAGE SHEDS ON PROPERTY WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

INSTALLED WATER SUPPLY LINES/SPRINKLER/SEWER LINES WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.18

INSTALLED WOOD FENCE WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15070786

CASE ADDR: 1437 NE 56 ST

OWNER: BRODETZKI, YUVAL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THE BUILDING HAS BEEN ALTERED WITHOUT A PERMIT. IT HAS BEEN CONVERTED TO FIVE UNITS. APPROVED USE IS FOR A SINGLE UNIT FAMILY RESIDENCE.

FBC(2014) 105.3.1.4.4

THE PLUMBING HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15

WINDOW AND DOOR INSTALLATIONS AND ALTERATIONS WITHOUT A PERMIT

FBC(2014) 105.4.1.2

OWNER OF RECORD IS RESPONSIBLE TO ABIDE BY FLORIDA BUILDING CODE AS OUTLINED IN FLORIDA STATUTES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC (2014) 111.4.1

PROPERTY IS A SINGLE FAMILY RESIDENCE APPROVED FOR SINGLE USE. THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY TO A FIVEPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15081055
CASE ADDR: 1208 NW 19 AV
OWNER: GREEN, LINDA
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HA

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED To:

- 1.INTERIOR REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS.
- 2. BUILDING A SHED IN THE BACK YARD WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING AN IRRIGATION SYSTEM WITH WELL PUMP AND TIMER WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING ELECTRICAL FOR IRRIGATION SYSTEM WITH WELL PUMP AND TIMER WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.11

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING AN AIR CONDITIONING CONDENSER UNIT WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15081207 CASE ADDR: 509 SW 6 ST

OWNER: JULIANNA & JOHN DOHERTY IRREV TR

DOHERTY, JULIANNA & JOHN TRSTEES

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED FRAMING AROUND WINDOWS.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW WINDOWS ON SIDE OF STRUCTURE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15082061

CASE ADDR: 86 ISLE OF VENICE
OWNER: SANTIAGO'S HOUSE LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW WOOD DECK WITHOUT OBTAINING THE REQUIRED PERMTS.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW TOILET FIXTURE WITHOUT OBTAINING THE REQUIRED PERMIT. IT IS NOW BACKED UP AND UNSANITARY.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS AND DOORS WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE15092128 CASE ADDR: 216 NW 8 AVE

OWNER: VILLANUEVA, ROBERTO

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR HAS BEEN GUTTED AND HOME IS BEING REMODELED.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. INTALLATION OF NEW PLUMBING INCLUDING FIXTURES.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. INSTALLATION OF WIRING, SWITCHES, OUTLETS, BOXES AND BREAKERS.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF WINDOWS AND DOORS.

FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF FENCE WITHOUT HAVING PERMIT ISSUED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS.

CASE NO: CE15090546
CASE ADDR: 1829 SW 11 ST
OWNER: LANIGAN, THOMAS P

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BATHROOM ALTERATIONS TO THE WALL STRUCTURE REQUIRING PERMIT.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FIXTURES REQUIRING A PERMIT

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. NOT LIMITED TO:

1. CHANGEOUT OF ELECTRICAL FIXTURES REQUIRING PERMIT.

FBC(2014) 105.3.1.4.17

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. GARAGE DOOR INSTALLATION REQUIRING A PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15092413 CASE ADDR: 1536 NW 5 AV

OWNER: MERCADO, REINALDO J PEREZ H/E

KARAMANOGLOU, ALEX

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. EXTENSIVE REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS MAY BE CITED IF DISCOVERED DURING THE CONSTRUCTION PROCESS. THIS INCLUDES STRUCTURAL ALTERATIONS MADE TO THE ROOF AND WALL STRUCTURE OF THE BUILDING.

FBC(2014) 105.3.1.4.3

THE FOLLOWING WORK REQUIRES A DEMOLITION PERMIT AND INSPECTIONS:

1. COMPLETE INTERIOR DEMOLITION HAS BEEN PERFORMED PRIOR TO OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. PLUMBING ALTERATIONS, MODIFICATIONS, HAVE COMMENCED PRIOR TO OBTAINING THE REQUIRED PERMITS. THIS INCLUDES FIXTURES, SUPPLY LINES, WASTE DISPOSAL, IRRIGATION AND R & R SINKS/WATER BASINS.

FBC(2014) 105.3.1.4.5

THE FOLLOWING WORK REQUIRES AN ELECRICAL PERMIT AND INSPECTIONS:

1. THE INSTALLATION OF NEW ELECTRICAL PANEL, LIGHT FIXTURES, RE-WIRING, WALL OUTLETS, SWITCHES, AC SUPPLY AND METER BASE.

FBC(2014) 105.3.1.4.10

THE FOLLOWING WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. RE-ROOFED THE STRUCTURE PRIOR TO OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. THE REPLACEMENT OF THE EVAPORATOR UNIT, THERMOSTAT, THE CONDENSER UNIT, ALL REGISTERS AND ELECTRICAL CIRCUITS.

FBC(2014) 107.1.1

SUBMITTAL OF 2 SETS OF PLANS AND SPECIFICATIONS AS OUTLINED IN THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF \$500 PER DAY FOR VIOLATIONS OF THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED.

WORK WITHOUT PERMITS DEEMED THIS BUILDING AS UNSAFE AND SUBJECT TO BOARD-UP AND/OR DEMOLITION UNDER THE SECTION OF THIS CODE.

CASE NO: CE15101425

CASE ADDR: 640 TENNIS CLUB DR # 308

OWNER: RUBINSTEIN, GARY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS. REMOVAL OF KITCHEN CABINETS AND ALTERATION OF SOFFITS AND CEILING.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

1. SINK HAS BEEN REMOVED AND THE PLUMBING SYSTEM HAS BEEN MODIFIED.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

1. OUTLETS AND FIXTURES HAVE BEEN REMOVED AND THE ELECTRICAL SYSTEM MODIFIED.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK,

ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM. 1. DUCT WORK HAS BEEN MODIFIED.

FBC (2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF UP TO \$500 PER DAY PER VIOLATION UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE15101515
CASE ADDR: 1107 NW 11 ST
OWNER: RIVERO, FACUNDO

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING.
- 2. DRYWALL HAS BEEN INSTALLED.
- 3. BEARING WALLS ARE BEING ALTERED.
- 4. NON-BEARING WALLS HAVE BEEN ALTERED.
- 5. PARTITIONS HAVE BEEN MOVED.
- 6. INTERIOR FLOOR PLAN CONFIGURATION HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR DEMOLITION OF NON-BEARING WALLS.
- 2. INTERIOR DEMOLITION OF BEARING WALLS.
- 3. DRYWALL HAS BEEN REMOVED AND REPLACED.

FBC (2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. WATER SPIGOTS ON EXTERIOR OF DWELLING HAVE BEEN REPLACED.
- 2. NEW WASTE LINES AND CLEANOUTS HAVE BEEN INSTALLED.
- 3. NEW WATER SUPPLY LINES IN LAUNDRY ROOM, KITCHEN AND BATHROOMS.
- 4. PLUMBING FIXTURES ARE BEING REPLACED IN KITCHEN, BATHROOMS AND LAUNDRY ROOMS.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CIRCUITS IN BREAKER PANEL ARE ARE BEING MODIFIED.
- 2. NEW CIRCUITS ARE BEING INSTALLED IN KITCHENS, BATHROOM, LAUNDRY ROOM AND OTHER LIVING AREAS.
- 3. NEW FIXTURES ARE BEING INSTALLED IN KITCHENS, BATHROOM, LAUNDRY ROOM AND OTHER LIVING AREAS.
- 4. SWITCHES AND OUTLETS ARE BEING REPLACED AND MODIFIED.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF UP TO \$500 PER DAY PER VIOLATION UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE15101733

CASE ADDR: 1216 CHATEAU PARK DR

OWNER: S R SINGH ENTERPRISES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ALTERATIONS BY ENCLOSING THE GARAGE OF THE STRUCTURE.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS WILL REQUIRE PERMITTING.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FIXTURES INCLUDING WATER HEATER.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL FIXTURES, SWITCHES AND OULETS.
- 2. CIRCUITRY FOR WATER HEATER.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16021479 CASE ADDR: 527 N BIRCH RD

OWNER: BEACH HOUSE VILLAS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: 47-20.20.I.

1. SEAL COATING AND RESTRIPING PARKING AREA.

FBC (2014) 105.1

THIS BUILDING/FACILITY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SEAL COATING AND RESTRIPING PARKING AREA.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16032371 CASE ADDR: 2327 SW 17 AVE OWNER: JANDEBEUR, PATRICK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. BUILT SCREEN ENCLOSURE STRUCTURE AT BACK

ELEVATION OF BUILDING.

2. CONSTRUCTION OF SCREEN ENCLOSURE STRUCTURE IN PROGRESS AT RIGHT ELEVATION OF BUILDING.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16021515
CASE ADDR: 2961 SW 19 AVE
OWNER: KEYSTONE HALLS INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. COMPLETE DEMOLITION OF THE STRUCTURE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16030350
CASE ADDR: 1535 NW 10 AV

OWNER: WASHINGTON, JEANETTE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW PLUMBING AT BACK OF PROPERTY.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW ELECTRICAL 220V OUTLET.

FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. MODIFIED EXISTING FENCE FROM ORIGINAL APPROVED CONFIGURATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16010842 CASE ADDR: 2312 NW 14 ST OWNER: PERSAUD, OMCHAND

INSPECTOR: JOSE ABIN

VIOLATIONS: 9-259

WATER DAMAGE FROM LEAKING ROOF HAS MADE THE RESIDENCE UNINHABITABLE. CEILING HAS FALLEN EXPOSING RAFTERS.

FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BUILT A SECOND BATHROOM.
- 2. BUILT CHASES TO CONCEAL DUCT WORK PERMITS REQUIRED:
 - 1. BUILDING
 - 2. ELECTRICAL
 - 3. MECHANICAL
 - 4. PLUMBING

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM. THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE

FOLLOWING MANNER, BUT NOT LIMITED TO: BATHROOM ADDITION:

- 1. ADDED TOILET.
- 2. ADDED VANITY SINK.
- 3. ADDED SHOWER WITH PAN.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING

ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SYSTEM HAS BEEN ALTERED AND THE WIRING MODIFIED. FLIPPING ALL THE BREAKERS TO THE OFF POSITION DOES NOT DISCONNECT THE POWER TO ALL FIXTURES AND OUTLETS.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: CENTRAL A/C SYSTEM

- 1. NEW CONDENSOR UNIT. MANUFACTURED DATE 08/2015.
- 2. NEW EVAPORATOR UNIT. MANUFACTURED DATE 08/2015.
- 3. ADDED EXHAUST VENT IN BATHROOM ADDTION.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS ISSUED AFTER WORK HAS COMMENCED, AFTER THE FACT, TO BE DOUBLE FEE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT, THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 116.2.1.2.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

ELECTRICAL SYSTEM HAS BEEN ALTERED AND THE WIRING MODIFIED. FLIPPING ALL THE BREAKERS TO THE OFF POSITION DOES NOT DISCONNECT THE POWER TO ALL FISTURES AND OUTLETS.

A LETTER FROM A CERTIFIED AND LICENSED ELECTRICIAN IS REQUIRED TO DEEM THE STRUCTURE SAFE FOR OCCUPANCY.

NEC(2005) 110.27

BREAKER PANEL HAS MISSING BLANKS AND LIVE PARTS ARE EXPOSED.

NEC (2005) 440.22 (C)

THE POWER SUPPLY AND THE A/C UNIT ARE NOT COMPATIBLE TO MANUFACTURERS SPECIFICATIONS AND CAUSES THE CIRCUITS TO OVERHEAT AND GIVE OFF A BURNING ODOR.

CASE NO: CE16040470
CASE ADDR: 605 SW 17 ST
OWNER: C4NAVIGATOR LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. IMPACT WINDOWS AND DOORS HAVE BEEN INSTALLED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF 2 FAMILY DUPLEX TO 3 FAMILY TRI-PLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE16040945
CASE ADDR: 738 NW 15 WY
OWNER: SIP REALTY 1 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. COMPLETE INTERIOR REMODEL.
- 2. RESTORED WALL FRAME AND INSTALLED DRYWALL.
- 3. CLOSED DOOR OPENINGS WITH WOOD FRAMING AND CMU UNITS.
- 5. REMODELED KITCHEN AND BATHS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW MECHANICAL CONDENSOR UNIT.
- 2. ILLEGALLY INSTALLED NEW MECHANICAL EVAPORATOR UNIT.
- 3. ILLEGALLY INSTALLED AIR CONDITIONING DUCT WORK.
- 4. WILL REQUIRE ALL BATHROOMS TO BE MECHANICALLY VENTED.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW DOORS EXTERIOR AND INTERIOR.
- 2. ILLEGALLY INSTALLED NEW WINDOWS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW SINKS IN KITCHEN AND BATH.
- 2. ILLEGALLY INSTALLED NEW FAUCETS IN KITCHEN AND BATHS.
- 3. ILLEGALLY INSTALLED NEW WATER SPIGOTS.
- 4. ILLEGALLY INSTALLED NEW WATER LINES.
- 5. ILLEGALLY INSTALLED NEW WASTE LINES.
- 6. ILLEGALLY INSTALLED NEW WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW LIGHTING FIXTURES.
- 2. ILLEGALLY INSTALLED NEW SWITCHES AND OUTLETS.
- 3. ILLEGALLY INSTALLED NEW 220 OUTLETS FOR DRYER AND STOVE.
- 4. ILLEGALLY INSTALLED NEW ELECTRICAL WIRING FOR MECHANICAL SYSTEM.
- 5. ILLEGALLY INSTALLED WIRING.
- 6. ILLEGALLY LOW VOLATGE WIRING FOR MECHANICAL THERMOSTAT.

FBC(2014) 105.3.1.5

SUBMIT 2 SETS OF "AS BUILT" ARCHITECTURAL DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 116.2.1.3.1

WORK ILLEGALLY COMMENCED AND/OR ILLEGALLY COMPLETED PRIOR TO OBTAINING THE REQUIRED PERMITS IS DEEMED AS UNSAFE AND SUBJECT TO HAVE THE STRUCTURE BOARDED UP AND/OR DEMOLISHED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE16010108 CASE ADDR: 1725 SW 5 ST

OWNER: PEDELTY, JEFFREY J

PEDELTY, PETER

NEW OWNERS: 4 STAR PROPERTY ACQUISITIONS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REBUILDING THE DOCK IN THE WATERWAY.
- 2. REBUILDING/RESTORING THE STRUCTURAL COMPONENTS OF THE ROOF STRUCTURE.

FBC (2014) 105.3.1.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:
SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS FROM A

DESIGN PROFESSIONAL AND WHICH INCLUDES THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS MADE TO THE DOCK AND THE ROOF.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOESN'T MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. WORK COMMENCED AND/OR COMPLETED PRIOR TO OBTAINING THE REQUIRED PERMITS IS DEEMED AS UNSAFE. THE STRUCTURAL COMPONENTS OF THE ROOF HAVE BEEN RESTORED.

CASE NO: CE16020557 CASE ADDR: 812 SW 15 AV

OWNER: SCHUMANN, MICHAEL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODEL OF INTERIOR LIVING AREAS.
- 2. REMODELED KITCHEN.
- 3. REMODELED BATHROOM AND TILED WET AREAS.
- 4. INSTALLED GATE AT FRONT ENTRY DOOR.
- 5. WOOD DECK AT BACK YARD.
- 6. PERMANENT CANOPY ATTACHED TO WALL AT FRONT WINDOW.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. REPLACED KITCHEN SINK WITH FIXTURES.
- 2. REPLACED BATHROOM VANITIES
- 3. REPLACED BATHROOM FIXTURES FOR SINKS AND SHOWERS.
- 4. REPLACED TOILETS.
- 5. NEW SPRINKLER MANIFOLD.
- 6. NEW WASTE LINES AND CLEANOUTS

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. REPLACED KITCHEN FIXTURES.
- 2. REPLACED BATHROOM FIXTURES.
- 3. REPLACED OUTLETS, GFI'S AND SWITCHES.
- 4. REPLACED LIGHTING FIXTURES.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE13080252

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR RENOVATIONS.

FBC (2010) 105.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM IS BEING ALTERED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14121723
CASE ADDR: 2879 NE 28 ST
OWNER: NOLAN, GERALD N
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE SUB-DIVISION OF THE HOUSE TO CREATE SEPARATE RENTAL UNITS WITHOUT OBTAINING THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED BY ADDING ELECTRICAL WIRING, DEVICES AND FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE MAIN A/C UNIT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT PERMITS BE OBTAINED, INSPECTED, PASSED AND CLOSED PRIOR TO COMPLYING AND CLOSING THIS CASE.

FBC(2010) 111.1.1

THIS CODE CASE WILL REQUIRE A NEW CERTIFICATE OF OCCUPANCY IF THIS HOUSE IS SUBDIVIDED INTO SEPARATE RENTAL UNITS.

CASE NO: CE15011493

CASE ADDR: 401 SW 4 AVE # 605

OWNER: TOTH, ILDIKO INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2010) 105.1

1. THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE DEMOLITION OF THE KITCHEN AND TWO BATHROOMS WITHOUT THE REQUIRED PERMITS.

2. THIS CONDO UNIT HAS ALSO BEEN ALTERED WITH THE COMPLETE REMODELING OF THE ENTIRE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO STRUCTURAL WORK BEING DONE WHICH INCLUDES BUT IS NOT LIMITED TO FRAMING, DRYWALL AND TILE BACKING BOARD WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELING OF THE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE RENOVATION OF THE ENTIRE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO ELECTRICAL WIRING BEING INSTALLED AND ALTERING THE EXISTING ELECTRICAL DEVICES AND SWITCHES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELING OF THE KITCHEN AND BATHROOMS INCLUDING BUT NOT LIMITED TO THE ALTERATION OF THE MECHANICAL DUCT WORK AND FANS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL FIRST REQUIRE THAT THE CONDO UNIT OWNER HIRE A LICENSED ARCHITECT OR ENGINEER TO PROVIDE A COMPLETE SET OF DRAWINGS TO ADDRESS ALL THE VIOLATIONS AND THE NEEDED CORRECTIONS. BECAUSE OF THE SEVERITY OF THE ELECTRICAL WORK THAT WAS DONE THIS WILL BE A REQUIREMENT IN ORDER TO OBTAIN PERMITS. THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL THE REQUIRED PERMITS, SCHEDULE AND PASS ALL THE REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15011944
CASE ADDR: 609 NE 8 AV

OWNER: ELITE HOME PARTNERS LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR AND EXTERIOR RENOVATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE FRONT DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.17

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE GARAGE DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE OUT ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091850

CASE ADDR: 200 S BIRCH RD # 1011
OWNER: FRENI MEHTA REV TR
MEHTA, FRENI TRST

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A COMPLETE RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. FULL KITCHEN REMODEL TO INCLUDE THE FRAMING DOWN OF THE KITCHEN CEILING AND INSTALLING DRYWALL.
- 3. FULL BATHROOM RENOVATION WITH INSTALLATION OF DRYWALL/TILE BACKING BOARD.
 THIS WORK HAS BEEN PERFORMED WITHOUT HE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE PLUMBING SYSTEM WHICH INCLUDE BUT IS NOT LIMITED TO:

- 1. INSTALLED A TANKLESS WATER HEATER.
- 2. CONVERTED THE TUB INTO A SHOWER.
- 3. REPLACED THE SHOWER VALVE.
- 4. REMOVED AND REPLACED ALL THE PLUMBING FIXTURES IN BOTH THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE ELECTRICAL SYSTEM WHICH INCLUDES BUT IS NOT LIMITED TO:

1. WIRING, OUTLETS, SWITCHES, DEVICES AND THE WIRING OF A TANKLESS WATER HEATER.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS CONDO UNIT AND THE CONDO BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATIONS AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES OR POSSIBLY QUADRUPLE FEES THAT WILL BE APPLY.

FBC(2014) 110.6

SCHEDULED AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED.

CASE NO: CE15100439 CASE ADDR: 2000 NE 17 WY

OWNER: SCHRONEN, GARY & PEGGY H/E

HOWELL, J

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A TIKI HUT BEING BUILT IN THE REAR OF THE PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15100973

CASE ADDR: 3000 E SUNRISE BLVD # 16B

OWNER: COPPOLA, PAUL INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS CREATING AN OPENING BETWEEN TWO SEPARATE CONDO UNITS WHERE THE CONDO UNITS ARE NOW JOINED TOGETHER WITHOUT THE CORRECT PERMIT TYPE, A UNITY OF TITLE AND/OR REQUIRED

REVISIONS AND INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13091180 CASE ADDR: 833 NW 19 AV

OWNER: BROWN, J M & SILLIE MAE EST

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. WINDOWS AND DOORS ARE BEING REPLACED.
- 2. A/C UNIT WAS REPLACED.
- 3. ELECTRICAL WORK DONE. DISCONNECTED BOX TO THE A/C.
- 4. PLUMBING WORK DONE. A DRAIN LINE WAS EXPOSED ON THE NORTH SIDE OF THE HOUSE DRAINING ONTO THE GROUND.

FBC(2010) 105.4.4

PLUMBING INSTALLED AND EXPOSED ON NORTH SIDE OF HOUSE AND DRAINING ONTO THE GROUND WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ELECTRICAL WORK INSTALLED, DISCONNECT TO A/C WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.15

WINDOWS AND DOORS INSTALLED WITHOUT THE REQUIRED

PERMIT OR INSPECTIONS.

CASE NO: CE15101220 CASE ADDR: 1230 NW 7 AV

OWNER: GALA INVESTMENTS GROUP LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. A COMPLETE INTERIOR REMODELING OF THE KITCHEN AND BATHROOM.
- 2. THERE IS A SECOND BATHROOM THAT WAS ILLEGALLY INSTALLED IN THIS HOUSE AND WAS NEVER PERMITTED. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM INCLUDING THE DUCT WORK BEING REMOVED AND REPLACED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE PLUMBING BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM WAS ADDED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE ELECTRICAL BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM ILLEGALLY ADDED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC (2014) 107.1.1

THIS PROPERTY AND CODE CASE WILL REQUIRE DRAWINGS PREPARED BY A DESIGN PROFESSIONAL TO ADDRESS AND PERMIT THE SECOND BATHROOM THAT WAS ILLEGALLY INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

CASE NO: CE15120410 CASE ADDR: 824 NE 20 AV

OWNER: HG MIDDLE RIVER INVESTMENTS LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS RENOVATIONS, PAVERS AND FENCE INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS AND MINI SPLIT A/C SYSTEMS INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120478

CASE ADDR: 209 N FTL BEACH BLVD

OWNER: SEASONS CONDO ASSN OF FT LAUD INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL AND REPLACEMENT OF A 25 TON A/C UNIT ON THE TOP FLOOR OF THIS CONDOMINIUM BUILDING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120488
CASE ADDR: 5501 NE 25 AVE
OWNER: ATLANTIC LOFT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF THE POOL DECK AREA WHERE A WALL AND WOOD FENCE WERE REMOVED AND AN ALUMINUM FENCE WAS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. AN ALUMINUM FENCE INSTALLED WITHIN FIVE FEET OF THE POOLS WATER EDGE WHICH REQUIRES AN ELECTRICAL BONDING AND THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

CASE NO: CE15120539

CASE ADDR: 3020 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL.
- 3. REBUILDING EXTERIOR STAIRS AND DECKS.
- 4. REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED. REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK IS BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK IS BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120540

CASE ADDR: 3024 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. WINDOWS AND DOORS BEING REPLACED.

2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL, REBUILDING EXTERIOR STAIRS AND DECKS, AND REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED AND REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16011026
CASE ADDR: 1009 NE 17 CT
OWNER: CONROY, KYLE
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS PROPERTY WAS ORIGINALLY PERMITTED AS A TWO FAMILY DWELLING AND WAS ILLEGALLY CONVERTED IN A TRIPLEX UNIT WITHOUT THE PROPERTY CERTIFICATE OF OCCUPANCY. THERE HAS BEEN EXTENSIVE REMODELING WORK DONE ON THIS BUILDING WHICH INCLUDES BUT IS NOT LIMITED TO WINDOWS AND DOORS REPLACED, KITCHEN AND BATHROOM REMODELED, LAYOUT OF THE BUILDING HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. PLUMBING ALTERATION MADE:
 - A. REMODELING KITCHENS, BATHROOMS, REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ELECTRICAL ALTERATIONS MADE:
 - A. ELECTRICAL PANELS REPLACED, DISCONNECTS INSTALLED, ELECTRICAL OUTLETS, SWITCHES, DEVICES REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITH REMOVING AND REPLACING THE A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16011103

CASE ADDR: 2624 NE 30 PL # 103B OWNER: WILLIAMS, ASHLEY DAWN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. RENOVATIONS AND WORK BEING DONE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL INSTALLED AND/OR ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS CONDO BUILDING/UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. HAVING MECHANICAL ALTERATIONS MADE WHERE A/C UNITS HAVE BEEN INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16011959

CASE ADDR: 2941 E LAS OLAS BLVD

OWNER: ILENE RICHMOND LIV TR TRST ETAL

LORRAINE VREELAND

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS DEMOLITION, FRAMING AND DRYWALL WORK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO PLUMBING DEMOLITION AND/OR ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS SUCH AS LOW VOLTAGE LIGHTING, CAMERAS, OUTLETS INSTALLED OR ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC (2014) 111.1.1

THIS PROPERTY HAS BEEN ALTERED WHERE THE PREVIOUS BUSINESS WAS ISSUED A CERTIFICATE OF OCCUPANCY FOR OPERATING AS A RESTAURANT UNDER AN ASSEMBLY USAGE CLASSIFICATION. THE BUSINESS CLASSIFICATION HAS NOW CHANGED TO A GROUP M MERCANTILE OCCUPANCY WITHOUT FIRST RECEIVING THE REQUIRED CHANGE OF USE AND ISSUED A NEW CERTIFICATE OF OCCUPANCY.

CASE NO: CE16040122

CASE ADDR: 2175 NE 56 ST # 214 YANOFSKY, STUART B OWNER:

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS OF THE KITCHEN AND BATHROOM MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16030745 CASE ADDR: 2200 NE 52 CT JAOUADI, OUALID INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR AND EXTERIOR ALTERATIONS INCLUDING THE KITCHEN, BATHROOMS, WINDOWS AND DOORS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16050190
CASE ADDR: 2100 S OCEAN LN

OWNER: POINT OF AMERICA CONDO COMMON AREA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE IN THE PUMP AND MACHINE ROOM WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC (2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16050534 CASE ADDR: 2900 NE 30 ST

OWNER: LAUDERDALE TOWER CONDO ASSN INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE REQUIRED WORK TO BE DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F./CODE CASE PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 116.2.1.2.2

THE BUILDING HAS AREAS WHERE THERE IS CONCRETE DETERIORATION WHICH INCLUDES BUT IS NOT LIMITED TO BALCONY RAILINGS FAILING WHICH HAS CREATED AN UNSAFE CONDITION FOR THE BUILDING AND POSES POTENTIAL LIFE SAFETY ISSUES FOR THE OCCUPANTS OF THIS BUILDING.

CASE NO: CE16050869

CASE ADDR: 5100 BAYVIEW DR # 106

OWNER: SPECIALE, MICHAEL P & SPECIALE, SUSAN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS DEMOLITION, FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS CONDO UNITS' MASTER BATHROOM HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES OR POSSIBLY FOUR TIMES THE FEE UNDER SECTION 9-47 THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16060234

CASE ADDR: 2715 N OCEAN BLVD #PHB OWNER: BOYACIOGLU, GARABAT

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. UNDER SECTION 9-47 FOUR TIMES THE PERMIT FEES MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16061714

CASE ADDR: 1400 NE 56 ST # 209 OWNER: DIXIE REALTY LLC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE TO THE KITCHEN AND BATHROOM BEING FULLY REMODELED INCLUDING FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE TO THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE TO THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 109.3.3

THE PROPERTY/CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

CASE NO: CE16070025

CASE ADDR: 401 RIVIERA ISLE 503 OWNER: BROOKS, CHRISTOPHER

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS, DEMOLITION AND REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE INCLUDING AN ELECTRICAL PANEL REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16070628

CASE ADDR: 2701 N OCEAN BLVD OWNER: EMBASSY TOWER INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT AT A MINIMUM WILL APPLY AND BASED ON THE CIRCUMSTANCES AND SEVERITY OF THE VIOLATIONS AND CITY RESOURCES INVOLVED THIS CASE MAY BE SUBJECT TO FOUR TIMES THE FEE UNDER SECTION 9-47. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071233

CASE ADDR: 1920 S OCEAN DR # 501

OWNER: BOURKE, DONALD INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL AND CHIPPING HOLES THROUGH A SOLID CONCRETE BEAM AND EXPOSING REBAR WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE INCLUDING INSTALLING A TANKLESS WATER HEATER WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT AT A MINIMUM WILL APPLY AND BASED ON THE CIRCUMSTANCES AND SEVERITY OF THE VIOLATIONS AND CITY RESOURCES INVOLVED THIS CASE MAY BE SUBJECT TO FOUR TIMES THE FEE UNDER SECTION 9-47. SCHEDULE AND PASS ALL REQUIRED

INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15061766
CASE ADDR: 1004 SW 7 ST
OWNER: SCHATZ, DAVID W
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVER INSTALLATION ON DRIVEWAY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE14090494

CASE ADDR: 1205 NE 3 AV

OWNER: BLAKE, HEATHER

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. BATHROOM REMODEL.

CASE NO: CE15040769

CASE ADDR: 409 N VICTORIA PARK RD

OWNER: STEWART, SCOTT

HABAYEB, ZIAD

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PERGOLA BUILT ON THE FRONT OF THE PROPERTY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15050401 CASE ADDR: 1820 NE 17 WAY

OWNER: FLORIDA CONFERENCE ASSN OF

SEVENTH DAY ADVENTISTS

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

1. THE STAIR RAILINGS WERE REPLACED.

2. A METAL STRUCTURE WAS ERECTED, LAYING PAVERS, BOTH ON THE BACK PATIO.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15050755 CASE ADDR: 1200 NW 9 ST OWNER: ASSIS HOMES LLC INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. SINGLE FAMILY RESIDENCE CONVERTED INTO A DUPLEX.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16030692

CASE ADDR: 3473 RIVERLAND RD

OWNER: CORMBD LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WINDOWS AND DOOR REPLACEMENT.

2. DOOR OPENING CLOSED OFF.

3. KITCHEN AND BATHROOMS RENOVATIONS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15071410 CASE ADDR: 2427 NE 8 ST

OWNER: JAMES, GORDON D & JUSTINE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CARPORT WAS ENCLOSED AND CONVERTED INTO A GARAGE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15080754

CASE ADDR: 1706 NW 14 CT

OWNER: TUCHOW, TYLER

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. GARAGE WAS CONVERTED INTO LIVING SPACE.
- 2. CONSTRUCTION OF A SECOND BATHROOM.
- 3. AIR CONDITIONING SYSTEM CHANGE OUT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15092395 CASE ADDR: 1213 NW 19 CT

OWNER: GAINES, JOHNNIE EST INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF SEVERAL WINDOWS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16010716

CASE ADDR: 1934 E SUNRISE BLVD

OWNER: 1930 SUNRISE INTEREST INC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

ALTERATION OF FIRE RATED PARTITION.
 ALTERATION OF ELECTRICAL SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16021212 CASE ADDR: 712 SW 15 AVE

OWNER: RIVERSIDE FLATS LLC INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ROOF COVERING REPLACEMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15010557

CASE ADDR: 1521 NW 8 AVE

OWNER: 1519 NW 8 AVE LLC

INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC 105.1

- 1. THE EXTERIOR WALL BEHIND THE A/C COMPRESSORS HAS BEEN ALTERED WITHOUT PERMITS CREATING AN UNSAFE CONDITION.
- 2. AT LEAST 1 OF THE KITCHENS HAS HAD THE CABINETS REPLACED WITHOUT A PLUMBING OR ELECTRICAL PERMIT.
- 3. THE WATER HEATER HAS BEEN REPLACED.
- 4. AT LEAST ONE BATHROOM SINK HAS BEEN REPLACED. ADDITIONAL VIOLATIONS MAY EXIST.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. A/C COMPRESSOR.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15011328
CASE ADDR: 6171 NW 34 TER

OWNER: PRISCIANTELLI, MICHAEL T

INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. STRUCTURES AT REAR OF PROPERTY BUILT WITHOUT PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15101042 CASE ADDR: 1815 SW 4 ST

OWNER: TRUESDALE, ANDREW INSPECTOR: FRANK ARRIGONI

PRESENTED BY INSPECTOR JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

INSPECTOR RALPH RILES REPORTED TO ME THAT DURING AN INSPECTION FOR REROOF AT THIS LOCATION FOR RENEWED PERMIT 06023197 HE FOUND WHAT APPEARED TO BE A SMALL ADDITION BUILT WITHOUT PERMIT. AFTER A REVIEW OF THE PERMIT HISTORY, PHOTOS FROM BCPA'S WEBSITE AND A SITE VISIT, I HAVE DETERMIND THIS: 1. STRUCTURE WAS BUILT WITHOUT PERMITS. THE WORK INCLUDES ELECTRICAL AND PLUMBING WORK.

FBC(2014) 110.6

APPROVAL REQUIRED. NO WORK SHALL BE DONE ON ANY PART OF A BUILDING OR STRUCTURE OR ANY, ELECTRICAL, MECHANICAL OR PLUMBING INSTALLATION BEYOND THE POINT INDICATED HEREIN ABOVE FOR EACH SUCCESSIVE INSPECTION UNTIL SUCH INSPECTION HAS BEEN MADE AND THE WORK APPROVED AND THE INSPECTOR HAS SO INDICATED ON THE PERMIT CARD OR AN INSPECTION RECORD PAD AT THE JOB SITE WHICH HAS BEEN APPROVED BY THE BUILDING OFFICIAL.

CASE NO: CE16032002 CASE ADDR: 2349 SW 34 TER

UNITED PROPERTIES OF S FL LLC

INSPECTOR: FRANK ARRIGONI PRESENTED BY INSPECTOR JOSE ABIN

FBC(2014) 105.1 VIOLATIONS:

> THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE EXISTING WALL AND CEILING COVERING WAS REMOVED FROM THE INTERIOR OF THE KITCHEN,
 - BATHROOMS, DINING AREA AND LIVING AREA.
- 2. THE CARPORT HAS BEEN CONVERTED TO LIVING SPACE.
- 3. THE FRONT PORCH HAS BEEN EXTENDED AT THE ENTRANCE.
- 4. STRUCTURAL BLOCK WALL CONSTRUCTED WITH NO TIE BEAM OR BOND BEAM REQUIRING ENGINEERING.

- 5. INSTALLATION OF SOLAR PANEL ON EXTERIOR OF STRUCTURE.
- WALL COVERING FOR TILED WET AREAS IN BATHROOM AND KITCHENS.
- 7. INTERIOR PARTITIONS CONSTRUCTED.
- 8. SOFFIT CONSTRUCTED FOR NEW DUCTWORK.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WATER HEATER.
- 2. REMOVAL AND INSTALLATION NEW PLUMBING FIXTURES IN KITCHEN AND BATHROOMS INCLUDING BUT NOT LIMITED TO SINKS, FAUCETS, TOILETS, BATHTUBS.
- 3. PLUMBING WASTE LINES.
- 4. WATER SUPPLY LINES.
- 5. 3 INCH SANITARY LINE RUN BELOW THE SLAB FROM BATH TO THE UNPERMITTED CARPORT ENCLOSURE.
- 6. WATER HEATER.
- 7. SUPPLY AND RETURN LINES FOR SOLAR PANELS.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. NEW ELECTRICAL SERVICE.
- 2. REWIRING AND INSTALLATION OF NEW CIRCUITS THROUGHOUT THE ENTIRE STRUCTURE.
- 2. WEATHERHEAD UNDER ROOF SOFFIT NOT PER NEC230.24.
- 3. WIRING FOR NEW ELECTRICAL FIXTURE INSTALLATIONS.
- 4. WIRING OF INSTALLATION OF NEW SWITCHES.
- 5. WIRING FOR NEW RECEPTACLE INSTALLATIONS.
- 6. WIRING FOR NEW WATER HEATER.
- 7. BREAKER PANEL INSTALLATION WITH ALL WIRING CIRCUITS.
- 8. RECESSED LIGHT INSTALLATION.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52
R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS:
WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL
BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. NEW INSTALLATION OF MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.
- 3. INSTALLATION OF EXHAUST FANS IN BATH AREAS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE, CODE OF ORDINANCES

CASE NO: CE15051584

CASE ADDR: 1621 NE 20 AV

OWNER: PIEKARSKI, JASON

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. THERE IS A CURRENT PERMIT#15042829, FOR DOOR AND WINDOW REPLACEMENTS. IT APPEARS THAT THEY ARE WORKING BEYOND THE SCOPE OF THE ISSUED PERMIT AS THE BATHROOM AND KITCHEN HAVE RENOVATIONS IN PROGRESS.
- 2. WATER HEATER HAS BEEN REMOVED FROM ITS APPROVED LOCATION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT

THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14081054

CASE ADDR: 1834 LAUD MANORS DR OWNER: WSC BRICKELL LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 2. THE DWELLING WAS RE-ROOFED.
- 3. THE EXISTING CARPORT THAT WAS BUILT WITH THE DWELLING WAS ENCLOSED INTO A LIVING SPACE.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.
- 5. INTERIOR RENOVATIONS AND ELECTRICAL AND PLUMBING UPGRADES WERE PERFORMED INSIDE THE KITCHEN AND BATHROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15070923 CASE ADDR: 216 ROSE DR

OWNER: CECERE, LEONARD & MARY M

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED CANOPY AND ANCHORED TO BUILDING WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED CARPORT AND CONVERTED INTO GARAGE WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS AT CARPORT ALTERATION WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.17

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED GARAGE DOOR TO CONVERTED CARPORT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE14031507 CASE ADDR: 416 SW 11 CT

OWNER: REYNOLDS, STUART L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

- 1. THE PROPERTY OWNER HAS CONVERTED THIS SINGLE FAMILY HOUSE INTO A DUPLEX RENTING OUT THE BACK AND FRONT TO TWO DIFFERENT FAMILIES. THEY HAVE ENCLOSED THE CARPORT AND HALLWAY LEADING TO ONE PART OF THE HOUSE TO CREATE THE NEW FLOOR PLAN.
- 2. THEY HAVE ADDED ELECTRIC OUTLETS AND PLUMBING FIXTURES IN THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THE CARPORT HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION CLASS U (UTILITY) TO R-3 (LIVING SPACE) WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15031679
CASE ADDR: 1501 NW 19 AVE
OWNER: GRANT FLA LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. FLORIDA ROOM WAS CONVERTED INTO A THIRD BEDROOM WITH A BATHROOM. THERE ARE 15 PEOPLE LIVING IN THE DWELLING AS PER CODE OFFICER QUINTERO.
- 2. THERE ARE NEW WINDOWS AND DOORS INSTALLED OR REPLACED ON THE PROPERTY.
- 3. A CENTRAL A/C SYSTEM UNIT INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14071821 CASE ADDR: 1070 NW 25 AV OWNER: LANDERS, MARIE H/E

TAYLOR, MARTHA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. SRT WORK DONE WITHOUT PERMITS. THIS PROPERTY HAS BEEN ALTERED BY THE OWNER ENCLOSING THE OPEN PORCH ON THE SOUTH SIDE OF THE DWELLING. IT IS BEING USED AS LIVING SPACE. (CMP)
- 2. THE WINDOWS WERE REPLACED IN THE OPENINGS.
- 3. STORAGE SHED WAS INSTALLED AT THE REAR OF THE DWELLING.
- 4. IN ADDITION, THE PROPERTY OWNER IS RENTING OUT ROOMS, INCLUDING THE ENCLOSED PORCH.

FBC(2010) 105.1.5

THE OWNERS ARE SELLING PREPARED FOOD TO THE PASSING PUBLIC FROM THE CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 1604.1

THE STRUCTURES FOR THE ROOF AND WALLS BELONGING TO THE SOUTH SIDE ENCLOSED PORCH DO NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS. ALSO, THE ADDITION ON THE EAST SIDE OF THE BUILDING WHICH HOUSES A WATER HEATER IS NOT BUILT STRONG ENOUGH TO RESIST THE WIND AND GRAVITY LOADS THAT MAY BE IMPOSED. THE CONSTRUCTION METHODS AND MATERIALS DO NOT CONFORM TO ANY CODE.

ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEMED TO BE UNSAFE AS PER FBC 116.1.2 AND THE CONSTRUCTION IS UNDERDESIGNED. IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO THE WIND'S UPLIFT.

CASE NO: CE14072166
CASE ADDR: 907 NW 12 TER
OWNER: HASAN, HABEER
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS AS FOLLOW:

- 1. THE OUTSIDE WALLS WERE RE-STUCCOED.
- 2. ELECTRICAL WIRES ARE EXPOSED IN THE METER CAN.
- 3. THE BATHROOM WINDOW AND THE EXTERIOR DOOR WERE REPLACED.
- 4. INTERIOR ALTERATIONS ARE IN PROGRESS: DRYWALL, PLUMBING AND ELECTRICAL FIXTURES HAVE BEEN REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14110356

CASE ADDR: 2612 BARBARA DR
OWNER: MONDANI, GLEN H/E
MONDANI, PENTELOPE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT. STOP WORK ISSUED.

THERE IS WORK IN PROGRESS WITH EXPIRED PERMITS:

- 1. COMPLETED RENOVATION INSIDE OF THE DWELLING.
- 2. AN ELECTRICAL GENERATOR WITH GAS OR LP SUPPLIED TO IT WAS INSTALLED. THREE GAS SUPPLY LINES RAN TO THE INTERIOR OF THE HOUSE.
- 3. THE GARAGE WAS DEMOLISHED AND A SERVANT'S QUARTERS WAS BUILT WITH ELECTRICAL AND PLUMBING ALTERATIONS.
- 4. HURRICANE SHUTTERS WERE INSTALLED.
- 5. AN EXTERIOR DOOR WAS REPLACED.
- 6. ALTERATIONS TO THE FRONT PORCH.
- 7. PAVERS IN THE DRIVEWAY WERE DONE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15040555
CASE ADDR: 810 NE 4 AV
OWNER: R W L 4 INC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING WAS APPROVED TO BE USED AS A WAREHOUSE. IT HAS BEEN ALTERED AND IS BEING USED AS A NIGHT CLUB. THERE IS AN OPEN BAR AND IT IS NOW A VENUE FOR MUSIC/COMEDY SHOWS.

- 1. SEVERAL WOOD STAGES WERE BUILT AT THE REAR AND THE BAR AREA.
- 2. ELECTRICAL LIGHTS WERE HUNG OVER THE OPEN YARD AND THE USE OF ELECTRICAL EXTENSIONS CORDS SUPPLYING POWER TO THE STAGE AREA.
- 3. THERE IS A KITCHEN AREA. THEY ARE NOT APPROVED TO SELL FOOD. A PERMIT IS REQUIRED AS PER FBC 105.1.5.
- 4. THE PARKING LOT AND THE TWO EXISTING BATHROOMS ARE NOT THE STANDARD REQUIREMENT OF THE ADA OR THE FBC ACCESSIBILITY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION FOR GROUP M TO AN ASSEMBLY GOUP A-2 OR A-3; WITHOUT OBTAINING THE REQUIRED PERMITS FOR A CHANGE OF USE AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15090051 CASE ADDR: 1216 NE 2 ST

OWNER: MAUS, ARTHUR J & KAREN N

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS

WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD

BARRIERS HAVE NOT BEEN APPROVED TO COMPLY WITH THE

FLORIDA CHILD PROTECTION ACT FS515.

1. ELECTRICAL PERMIT # 00070898 (WIRE IN PUMP

MOTOR, POOL LIGHT, GROUNDING).

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15110196
CASE ADDR: 1701 NW 14 CT
OWNER: 2771 LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNER'S DRAWINGS WITH THE WINDS PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC (2014) 2224.1 FOR CHAIN LINK AND FBC (2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT

LOCATION.

1. A WOOD FENCE WAS ERECTED AT THE PROPERTY

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14110272

CASE ADDR: 1311 SEMINOLE DR
OWNER: DANIELSSON, LEIF
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY IS BEING ALTERED WITH THE FOLLOWING

WORK BEING DONE WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT

LIMITED TO:

1. EXTERIOR WALL REPAIR.

NEW DOCK.
 NEW TIKI HUT.

4. WHAT APPEARS TO BE POST FOR A FENCE OR

TRELLIS.

5. REMOVING AND REPLACING A PAVER DECK.